


What Will Be Done: Your Chevrolet dealer will replace the driver's safety belt buckle assembly with one that does not have the energy-absorbing loop.

How Long Will The Repair Take? This service correction will take approximately 20 minutes. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

Contacting Your Dealer: Please contact your Chevrolet dealer as soon as possible to arrange a service date. Parts are available and instructions for making this correction have been sent to your dealer. Your Chevrolet dealer is best equipped to obtain parts and provide services to correct your vehicle as promptly as possible. Should your dealer be unable to schedule a service date within a reasonable time, you should contact the Chevrolet Customer Assistance Center at 1-800-630-2438. The deaf, hearing impaired, or speech impaired should call 1-800-833-2438 (utilizes Text Telephones, TTY).

If, after contacting the Chevrolet Customer Assistance Center, you are still not satisfied that we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590 or call 1-888-327-4236.



GM OWNER: Present this card to your GM dealer to help identify the correction required to your vehicle.
PLEASE CHECK (X) THE APPROPRIATE BOX IF ANY OF THE CONDITIONS LISTED BELOW ARE APPLICABLE.
SUPPLY THE INFORMATION REQUESTED AND RETURN IN THE ENVELOPE PROVIDED.

☐ I have never owned this vehicle ☐ Vehicle damaged beyond repair ☐ Vehicle stolen and not recovered
☐ Campaign Completed on Date ____/____/____ by ☐ Self ☐ Other ☐ Vehicle Sold/Traded/Returned to:

00000113111
03020

STATE OF UTAH MOTOR POOL
447 W 13800 S
DRAPER, UT 84020-8145

NEW OWNER/FIRM NAME _____
ADDRESS _____
CITY _____ STATE _____ ZIP CODE _____
(AREA CODE) PHONE NUMBER _____
OWNER SIGNATURE _____